

Message Text

UNCLASSIFIED

PAGE 01 KABUL 03172 260549Z
ACTION INT-05

INFO OCT-01 NEA-10 ISO-00 CCO-00 PASO-00 /016 W
-----055217 260551Z /11

R 260340Z APR 78
FM AMEMBASSY KABUL
TO SECSTATE WASHDC 7553

UNCLAS KABUL 3172

FOR: JON PETERSON, ALBUQUERQUE SEISMOLOGICAL LAB
USGS KIRKLAND AFB, EAST ALBUQUERQUE, NM 87115

E.O. 11652: N/A
TAGS: TPHY, AF
SUBJECT: REPLACEMENT PARTS KABUL SEISMIC STATION

LPN HELICORDER OUT OF SERVICE. DRUM DRIVE MOTOR TYPE
KYC-22TS 115V AND 60 HZ DEFECTIVE. PLEASE SEND TWO
DRUM DRIVE MOTORS AIR PARCEL POST BY POUCH.
SHRODER.
ELIOT

NOTE BY OC/T: PASSED ABOVE ADDRESSEE.

UNCLASSIFIED

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 jan 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: SPARE PARTS, PROCUREMENT, MOTORS
Control Number: n/a
Copy: SINGLE
Draft Date: 26 apr 1978
Decaption Date: 01 jan 1960
Decaption Note:
Disposition Action: n/a
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01 jan 1960
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978KABUL03172
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Expiration:
Film Number: D780177-1073
Format: TEL
From: KABUL
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1978/newtext/t19780416/aaaaamwt.tel
Line Count: 36
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: 28c72fa7-c288-dd11-92da-001cc4696bcc
Office: ACTION INT
Original Classification: UNCLASSIFIED
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 1
Previous Channel Indicators: n/a
Previous Classification: n/a
Previous Handling Restrictions: n/a
Reference: n/a
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 29 mar 2005
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: N/A
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 2845900
Secure: OPEN
Status: NATIVE
Subject: REPLACEMENT PARTS KABUL SEISMIC STATION LPN HELICORDER OUT OF SERVICE. DRUM DRIVE MOTOR TYPE KYC-22TS 115V AND 60 HZ DEFECTIVE. PLEASE SEND TWO
TAGS: TPHY, AF
To: STATE
Type: TE
vdkgvkey: odbc://SAS/SAS.dbo.SAS_Docs/28c72fa7-c288-dd11-92da-001cc4696bcc
Review Markings:
Sheryl P. Walter
Declassified/Released
US Department of State
EO Systematic Review
20 Mar 2014
Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014